RELEASE NOTES

MCM — RMS1551-01-J

These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. Please read the notes before attempting to use the new firmware.

1   PROBLEMS CORRECTED

1.1   Y2K incompatibility: a hard-coded '19' used at the beginning of a date string shown on the display during startup, has now been replaced with a '20'.

1.2   Y2K incompatibility: corrected an error in the subroutine that encodes the year information in the MS-DOS directory.

2   CONFIGURATION FILES

Configuration files for version RMS1551-01-I are completely compatible with this version (RMS1551-01-J), and can be used without modification.