RMS INSTRUMENTS
Data Recording Systems

6877-1 Goreway Drive
Mississauga, Ontario
Canada, L4V-1L9

Tel: (905) 677-5533
Fax: (905) 677-5030
e-mail: rms@rmsinst.com
http://www.rmsinst.com

RELEASE NOTES

GP300 GRAPHIC PRINTER / CHART RECORDER

Firmware Release RMS1780-00-J

These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. The notes include information about enhancements, adaptive changes, and corrections to known problems. Please read this documentation carefully.

NOTE: The checksum for FW Rev. RMS1780-00-J is: ***** 05337E40 *****

1. Fixed a problem that could under certain conditions trigger errors of type '03-X', while transmitting to the GP300 a significant volume of data, while operating in chart mode.

2. The new firmware supports the Min/Max mode of operation on *digital direct channels.*

3. New command to stop any on-going printing of ID-labels and/or messages, and re-start them all in-synch by reloading their initial counts.