6877-1 Goreway Drive Mississauga, Ontario Canada, L4V-1L9 Tel: (905) 677-5533 Fax: (905) 677-5030 e-mail: rms@rmsinst.com http://www.rmsinst.com

## **RELEASE NOTES**

## AARC500 Adaptive Aeromagnetic Real-Time Compensator DAARC500 DAS & Adaptive Aeromagnetic Real-Time Compensator

## Front End Firmware Release RMS1877-02-B

These release notes contain important information about the new firmware and how it will affect the performance of instruments in which it is installed. The notes include information about enhancements, adaptive changes, and corrections to known problems. Please read this documentation carefully.

## Compatibility:

AARC500 – requires Host firmware RMS1878-01-H or later DAARC500 – requires Host firmware RMS1936-01-G or later

1. Added protection to eliminate the possibility that spurious "triggers" be issued when using the external-PPS triggering mode, and the PPS input signal is < 1.0 Hz.