6877-1 Goreway Drive Mississauga, Ontario Canada, L4V-1L9 Tel: (905) 677-5533 Fax: (905) 677-5030 e-mail: rms@rmsinst.com http://www.rmsinst.com

RELEASE NOTES

SERIAL INTERFACE MODULE - RMS1527-01-E

1. MODIFICATIONS

1.1 The Serial Interface Module now supports bit rates up to 38.4 kbps. This has been implemented by replacing the 300-bps option, essentially never used in practice, with 38.4 kbps.

Note that the current MCM firmware (RMS1551-01-J) has not been modified to reflect this change. Therefore, one must select 300 bps through the operator interface of the DAS8/DGR33A in order to get 38.4 kbps.

2. COMPATIBILITY

Firmware revision RMS1527-01-E of the RMS4272A SIM Module requires revision RMS1551-01-C (or later) of the RMS4183A MCM. See also 1.1.